

# Case Study

## Engine Line Install

### The assignment

Greenfield installation of Customer Equipment into AE facility.

### The challenges

- Piston line
- Head line A (DI)
- Head line B (over/under conveyor)
- Block line A & B
- Main line A-D
- 8 Mezzanines
- 16 Elevators
- Approximately 100 robots
- 86 Automatic stations
- 1 Nut runner to be located from Plant 2

