

Case Study

Paint Shop Management + Technical Cleaning

Leadec has numerous technical cleaning service customers around the world. This case study represents one such operation in Louisville, KY.

The assignment

- Complete management of 6 paint lines
- 1,600 vehicles per day
- Skip cleaning, deep cleaning
- Skids, grates and fixtures removed, staged and reinstalled by Leadec

The customer

- Large automotive OEM

Scope of services

- 5 wet booths
- 1 dry booth + 5 zones
- 8 years on site

The outcome

- The only supplier recognized in 2016
- Highest first-run rate in company: Over 99.0%
- Net Promoter Score (NPS): 9.5/10
- 6% cost savings per year

